



STELLARGOLD DAC

RELEASE NOTES

Version 2.7.0
Date 9/4/2024
File stgold_dac_v2.7.0.bin
image.bin

Description

Bug fixes.

Fixes

- Fixed volume would not work when changing inputs
- Some settings were not properly restored on power on
- Startup wizard would set volume to 100 inadvertently
- Added pop-up to indicate a reboot after a factory reset
- Other minor fixes

Version 2.6.3
Date 6/3/2024
File stgold_dac_v2.6.3.bin
image.bin

Description

Bug fixes.

Fixes

- Filter icon would not appear correctly
- Fixed Volume not restored after power cycle

Version 2.6.1
Date 2/23/2024
File stgold_dac_v2.6.1.bin
image.bin

Description

Bug fixes.

Fixes

- More fixes for display being cut-off on the right
 - Fixed issues with input lock
 - Fixed filter icon not showing
 - Fixed pre-emphasis
 - Added pre-emph to menus
 - Minor bug fixes
-

Version 2.5.2
Date 11/06/2023
File stgold_dac_v2.5.2.bin

Description

Fixes many beta issues.
Changed the binary file name to stgold_dac_vX.Y.X.bin.

Fixes

- STLR-1132 The display is partially obscured on the right-hand side
 - STLR-1147 Can't get to Factory Reset menu
 - STLR-1148 Issues with Remote performance
 - STLR-1155 CD shows as 24 bits instead of 16
 - STLR-1172 Triggers aren't working
 - STLR-1178 Add filter control to IR
 - STLR-1188 Fix bit depth display
 - STLR-1202 Enable phase from remote
-

Version 2.4.6
Date 10/13/2023
File stellar_dac_v2.4.6.bin

Description

Fixes issues in beta with IR and selecting Coax inputs.

Fixes

- STLR-1148 Issues with Remote performance
- STLR-1188 Coax 1 and Coax 2 buttons on the remote were not functioning

Known Issues

- STLR-1131 In minimal display mode the display reads “infobar” at the top
- STLR-1132 The display is partially obscured on the right hand side
- STLR-1134 Can't tell when you are in sub-menus
- STLR-1155 Bitrate not displaying correctly

Version 2.4.2
Date 09/28/2023
File stellar_dac_v2.4.2.bin

Description

Initial beta release.

Fixes

Initial Release